CXA-KOMU/CXV-KOMU
Mount Plate
Instructional Manual

Introduction:

Thank you for your choice in purchasing a Core SWX mount plate. The mount plate is designed to improve and assist you in your mobile powering requirements. This product is at the pinnacle of technological advancements, offering the features and performance of several different products, making it the most advanced mount plate product in the industry.

Please read this manual to help you understand and capitalize on the features of this mount plate.

Features:

- Plate connects directly to camera via BP Mount
- 3 DC output ports: P-Tap, USB-A, and 2pin Lemo
- Reinforced mount locking mechanism
- Micro USB firmware update port
- Red/Green indicator LED
- Compatible with 14.4V batteries
- Capable of passing smart CoreSWX battery data to camera

Operation:

1. Connect to any RED® KOMODO™ camera by connecting directly to BP Mount.
2. The battery can then be inserted into the mount plate to provide a direct connection to accept battery packs.
3. Once the battery is connected, the LED will indicate the presence of voltage passing through the plate

LED Indication Guide:

Battery State	LED Indication
Low Battery	Solid RED
Battery Connected	Solid GREEN

Specification Data:
CXV-KOMU: V-mount Connection
CXA-KOMU: 3-Stud Mount Connection

Input: 11.9vdc-16.8vdc
Output for camera: DC 7.4v, Dual Canon BP backing
Powertap: DC 11.9-17v, Unregulated
2p Lemo: DC 11.9-17v, Unregulated
USB: DC 5v, Unregulated
Size: 4.6″ x 3.58″ 1.5″
Weight: 0.4 lbs
Firmware port: USB Micro
LED power indication: Bi-color(red/green)

Warranty:

This product is warranted to the Original Purchaser against all defects in material and or workmanship for the period herein.

The warranty period shall be 1 years for parts and labor, unless otherwise noted. Core SWX agrees to pay equal return freight costs to return the product the same method it was received. In the event of an issue, the purchaser agrees to the below RMA procedure.

Procedure:

1. Go to http://www.coreswx.com and to the the support section to fill out the online RMA form.
2. Print the RMA number confirmation, and ship the product needing service to Core SWX, LLC. along with RMA number confirmation, and copy of bill of sale.
3. All shipments must be done either through UPS or FEDEX, and insured if necessary
4. Core SWX, LLC. is not responsible for any lost shipments.

Core SWX reserves the right to repair or replace any defective product under warranty after Core SWX determines which is more practical.

If Core SWX receives defective product for warranty repair and they are found to be defective as a result of misuse or other damage, not caused by normal wear and tear, Core SWX will notify the customer of an estimate of repair. Customer will incur costs. There are no further warranties, either expressed or implied, including warranties of merchantability or fitness for a particular purpose that has any bearing upon this transaction.

91B Commercial St.   Plainview NY 11803 USA

Web: www.coreswx.com   Email: sales@coreswx.com

Tel: +1 516-595-7488   Fax: +1 516-595-7492

Copyright © 2024
All rights reserved

Disclaimer

The information contained in this manual is believed to be correct at the time of issuance. Core SWX, LLC. reserves the right to make the changes to the information or specifications without obligation to notify any person of such revisions or changes. Changes will be incorporated in new versions of the manual.

Core SWX, LLC. reserves the right to make changes to product design and functionality without notification.

Trademarks

All product trademarks and registered trademarks are the property of Core SWX, LLC. All other trademarks and registered trademarks are the property of the respective companies.

Patents

The following US patents apply 10,197,630 and 10,630,095.